

## CYBER SECURITY NOTIFICATION

### **PEPPERL+FUCHS: (Update A) Multiple Products / Control RocketLinx® – Multiple Vulnerabilities may allow remote attackers access, program execution and to tap information**

Document ID TDOCT-6954A\_ENG  
 Publication date 2021-02-22

Update of:  
 Document ID TDOCT-6954\_ENG  
 Publication date 2020-10-05  
 Reason for update New firmware provided as a solution

#### **Vulnerabilities or CVE Identifier**

<b>Identifier</b>	<b>Vulnerability Type</b>	<b>Description</b>
CVE-2020-12500	CWE-285: Improper Authorization	Unauthenticated Device Administration
CVE-2020-12501	CWE-798: Use of Hard-coded Credentials	Undocumented Accounts
CVE-2020-12502	CWE-352: Cross-Site Request Forgery (CSRF)	Cross-Site Request Forgery (CSRF)
CVE-2020-12503	CWE-20: Improper Input Validation	Multiple Authenticated Command Injections
CVE-2020-12504	CWE-912: Hidden Functionality	Active TFTP-Service

#### **Severity**

<b>Identifier</b>	<b>Base Score and Vector</b>
CVE-2020-12500	9.8 (CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H)
CVE-2020-12501	9.8 (CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H)
CVE-2020-12502	8.8 (CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:H/I:H/A:H)
CVE-2020-12503	7.2 (CVSS:3.1/AV:N/AC:L/PR:H/UI:N/S:U/C:H/I:H/A:H)
CVE-2020-12504	9.8 (CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H)

#### **Affected products**

P+F Control RocketLinx®:  
 ES7510-XT, ES8509-XT, ES8510-XT, ES9528-XTv2,  
 ES7506, ES7510, ES7528, ES8508, ES8508F, ES8510, ES8510-XTE,  
 ES9528/ES9528-XT

## Summary

Several critical vulnerabilities within Firmware.

## Impact

Pepperl+Fuchs analyzed and identified affected devices.

Remote attackers may exploit multiple vulnerabilities to get access to the device and execute any program and tap information.

## Solution

Take the following steps to address vulnerabilities CVE2020-12500, CVE2020-12501, CVE2020-12502, CVE2020-12503 and CVE2020-12504 on the ES7510-XT and ES8510-XT switches:

Step 1) Update following products to the respective Firmware Version:

Item	Firmware Version
ES8510	3.1.1
ES7510-XT	2.1.1

Step 2) Deactivate TFTP-Service

Step 3) Deactivate PortVision DX Protocol

For the other affected products, an external protective measure is required:

- Minimize network exposure for affected products and ensure that they are not accessible via the Internet.
- Isolate affected products from the corporate network.
- Traffic from untrusted networks to the device should be blocked by a firewall. Especially traffic targeting the administration webpage
- If remote access is required, use secure methods such as virtual private networks (VPNs).
- Administrator and user access should be protected by a secure password and only be available to a very limited group of people.

## Reported by

T. Weber (SEC Consult Vulnerability Lab)

<https://www.sec-consult.com/en/vulnerability-lab/advisories/index.html>

Coordinated by CERT@VDE

## Support

For support please contact your local Pepperl+Fuchs sales representative.