

■ CYBER SECURITY NOTIFICATION

PEPPERL+FUCHS: Multiple DTM and VisuNet Software – Vulnerability may allow local authorized attackers access and remote code execution on the target device

Document ID TDOCT-7494_ENG
 Publication date 2021-10-25

Vulnerabilities

| Identifier | Vulnerability Type | Description |
|---------------|--|---|
| CVE-2018-1285 | CWE-611: Improper Restriction of XML External Entity Reference | Apache log4net versions before 2.0.10 do not disable XML external entities when parsing log4net configuration files. This allows for XXE-based attacks in applications that accept attacker-controlled log4net configuration files. |

Severity

| Identifier | Base Score and Vector |
|---------------|--|
| CVE-2018-1285 | 9.8 (CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H) |

Affected DTM products

| Item | Item Version | DTM / Component | DTM / Component Version |
|-------------------------------|-------------------------|--------------------------------|-------------------------|
| FieldConnex DTM Collection | 1.7.0.2146 and previous | HD2-GTR-4PA DTM | 2.0.5 to 2.0.12.2146 |
| | | HD2-GTR-4PA.PN DTM | 1.0.4.2146 and previous |
| | | PROFINET IO Communication DTM | 1.0.4.2146 and previous |
| | | *D0-MIO-Ex12.PA.* DTM | 1.0.3.2146 and previous |
| | | *D0-TI-Ex8.PA.* DTM | 1.1.3.2146 and previous |
| | | ARS11-*-* DTM | 1.0.1.2146 and previous |
| Honeywell Integration Package | 1.1.2.0 and previous | ADM Project Builder Honeywell | 1.0.2.1418 and previous |
| | | FieldConnex Diagnostic ActiveX | 2.2.2.3478 and previous |
| | | FieldConnex Diagnostic Server | 2.2.2.3086 and previous |
| Emerson Integration Package | N/A | ADM Project Builder Emerson | 1.1.3.1463 and previous |
| | | AMS Alert Adapter | 1.1.2.69 and previous |

| Item | Item Version | DTM / Component | DTM / Component Version |
|--|--------------------------|-----------------------|--------------------------|
| Diagnostic Manager | 2.0.0.1177 to 2.2.2.3478 | All contained DTMs | 2.0.0.1177 to 2.2.2.3478 |
| FieldConnex Diagnostic Gateway FF DTM | 2.2.2.3478 and previous | All contained DTMs | 2.2.2.3478 and previous |
| FDH-1 Manager | 1.0.1.1022 and previous | N/A | N/A |
| ABB Project Builder | 1.1.1.1122 and previous | N/A | N/A |
| DTM Collection HART-Multiplexer | 2.0.0.130 and previous | All contained DTMs | N/A |
| TMI-FF DTM | 2.6.3.10 and previous | All contained DTMs | N/A |
| HART DTM Library Enhanced used with PS3500-DM | 2.4.11.26 and previous | All contained DTMs | N/A |
| DTM used with S1SD-1TI-1U | N/A | P+F DTMLibrary Modbus | V2.3.4.68 |
| DTM Library HART used with 6500 Series | 2.4.11.59 and previous | All contained DTMs | N/A |
| DTM Collection Level Control Technology used with Level Radar LCR20, LTC50, LTC51, LRC57 | 1.0.31 and previous | All contained DTMs | N/A |
| DTM Collection WirelessHART | 1.0.2.4 and previous | All contained DTMs | N/A |

Affected VisuNet products

| Item | Version |
|-----------------------------|--------------------|
| VisuNet RM Shell | 5.5.0 and previous |
| VisuNet Factory Reset | 5.x |
| VisuNet Factory Reset | 6.1.0 and previous |
| VisuNet Control Center | 4.7.1 and previous |
| VisuNet GXP PC Service Tool | 1.1.0 and previous |

Summary

Critical vulnerabilities have been discovered in the utilized component log4net by Apache Software Foundation.

Impact

Pepperl+Fuchs analyzed and identified affected devices.

In table “Affected products” packages are listed next to some products, this means that the products are only affected if the corresponding software is installed since the package implements the vulnerability.

To exploit the vulnerability, the access rights of an authorized user or admin are required.

The impact of the vulnerability on the affected products may result in

- denial of service
- loss of credentials
- code execution

The CVSS environmental score is specific to the customer's environment and should therefore be individually assessed by the customer to accomplish final scoring.

The original CVE refers to a network access scenario. With our products, it is a local access scenario. For this reason, the risk of exploiting this vulnerability is reduced.

Solution

The following affected DTM products can be updated to the listed version:

| Item | Version |
|--|------------|
| FieldConnex DTM Collection | 1.7.1.2159 |
| Diagnostic Manager | 2.2.3.3527 |
| FieldConnex Diagnostic Gateway FF DTM | 2.2.3.3527 |
| FDH-1 Manager | 1.0.2.1049 |
| ABB Project Builder | 1.1.2.1134 |
| Honeywell Integration Package | 1.1.3.0 |
| Emerson Integration Package [ADM Project Builder Emerson] | 1.1.4.1474 |
| Emerson Integration Package [AMS Alert Adapter] | 1.1.3.72 |
| DTM Collection HART-Multiplexer | 2.0.1.208 |

External countermeasures are needed for the remaining products.

The following protective measure is required for VisuNet devices and the PCs/Servers with an installed DTM:

- Restrict local access to the device, PC/Server and use user authentication to prevent unauthorized access.

Reported by

CodeWrights GmbH
Coordinated by CERT@VDE

Support

For support please contact your local Pepperl+Fuchs sales representative.