

# FIMlet Ethernet-APL Switches

Software Release Notes

## Software Details

Software Name:	FIMlet Ethernet-APL Switches
Release Version:	1.5.74
Release Date	27/Jun/2024
Description	FIMlet for Pepperl+Fuchs Ethernet-APL Switches to be used with ABB Ability™ Field Information Manager (FIM)

## 1. Software Version 1.5.74

### 1.1 Supported Products

- ARS\*-\*-IC\*-\* , requires at least PANOS firmware version 1.3.0
- ARS\*-\*-IA\*-\* , requires at least PANOS firmware version 1.3.0

### 1.2 New features

- Update of FDI Device Packages to version 1.5.146

### 1.3 Changed features

- None

### 1.4 Bug Fixes

- ABB FIM may get stuck if PA devices are moved from one spur to another

## 2. Software Version 1.4.69

### 2.1 Supported Products

- ARS\*-\*-IC\*-\*, requires at least PANOS firmware version 1.2.0
- ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.2.0

### 2.2 New features

- FIM Bridge 800xA is supported

### 2.3 Changed features

- Update of FDI Device Packages to version 1.4.128

### 2.4 Bug Fixes

- None

## 3. Software Version 1.3.58

### 3.1 Supported Products

- ARS\*-\*-IC\*-\* , requires at least PANOS firmware version 1.2.0
- ARS\*-\*-IA\*-\* , requires at least PANOS firmware version 1.2.0

### 3.2 New features

- None

### 3.3 Changed features

- Update of FDI Device Packages to version 1.3.103

### 3.4 Bug Fixes

- None

## 4. Software Version 1.2.46

### 4.1 Supported Products

- ARS\*-\*-IC\*-\* , requires at least PANOS firmware version 1.1.1
- ARS\*-\*-IA\*-\* , requires at least PANOS firmware version 1.1.1

### 4.2 New features

- None

### 4.3 Changed features

- Update of FDI Device Packages to Version 1.2.85 because of GSDML file and product documentation updates

### 4.4 Bug Fixes

- None

## 5. Software Version 1.2.38

### 5.1 Supported Products

- ARS\*-\*-IC\*-\*, requires at least PANOS firmware version 1.1.1
- ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.1.1

### 5.2 New features

- FIMlet is digitally signed

### 5.3 Changed features

- Product documentation is added to the FIMlet
- Spur numbers are shown for connected PROFIBUS PA devices
- FDI Device Package for Ethernet-APL Field Rail Switch ic upgrade to Version 1.2.83
- FDI Device Package for Ethernet-APL Field Rail Switch ia upgrade to Version 1.2.83

### 5.4 Bug Fixes

- Scanning of PROFIBUS PA device fails if the device contains invalid content in its I&M data
- ABB Field Information Manager dashboard is not able to access multiple PROFIBUS PA field devices at the same switch

## 6. Software Version 1.1.27

### 6.1 Supported Products

- ARS\*-\*-IC\*-\*, requires at least PANOS firmware version 1.1.0
- ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.1.0

### 6.2 Changes

- Initial Release

# Your automation, our passion.

## Explosion Protection

- Intrinsic Safety Barriers
- Signal Conditioners
- FieldConnex® Fieldbus
- Remote I/O Systems
- Electrical Ex Equipment
- Purge and Pressurization
- Industrial HMI
- Mobile Computing and Communications
- HART Interface Solutions
- Surge Protection
- Wireless Solutions
- Level Measurement

## Industrial Sensors

- Proximity Sensors
- Photoelectric Sensors
- Industrial Vision
- Ultrasonic Sensors
- Rotary Encoders
- Positioning Systems
- Inclination and Acceleration Sensors
- Fieldbus Modules
- AS-Interface
- Identification Systems
- Displays and Signal Processing
- Connectivity

Pepperl+Fuchs Quality  
Download our latest policy here:

[www.pepperl-fuchs.com/quality](http://www.pepperl-fuchs.com/quality)

