


Mounting aid OMH-RL28-C


- Protection from welding beads
- Simple and fast mounting



Weld slag cover model

Dimensions





Technical Data

| General specifications | |
|---------------------------|-----------------------------------|
| Accessories provided | glass M4 x 8 mm thumb screw |
| Mechanical specifications | |
| Material | |
| Housing | Metal sheet (steel), black-coated |
| Optical face | glass |
| Suitable series | |
| Series | RL28 RL29 |
| | |

Refer to "General Notes Relating to Pepperl+Fuchs Product Information"

Pepperl+Fuchs Group www.pepperl-fuchs.com USA: +1 330 486 0001 fa-info@us.pepperl-fuchs.com Germany: +49 621 776 1111 fa-info@de.pepperl-fuchs.com Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com



Mounting aid

Step 1

Push lens into the lip on the housing as shown.Rotate lens into position as shown.

Caution: Glass lens is fragile, handle with care



Step 2

• After lens has been rotated into it's correct position. Secure it as shown below. Caution: Do not over tighten, glass lens is very fragile.



Refer to "General Notes Relating to Pepperl+Fuchs Product Information"

