CERTIFICATE OF COMPLIANCE

Certificate Number 20141115-E223772

Report Reference E223772-20000724

Issue Date 2014-NOVEMBER-15

Issued to: PEPPERL+FUCHS GMBH

LILIENTHALSTRASSE 200 68307 MANNHEIM GERMANY

This is to certify that PROGRAMMABLE CONTROLLERS

representative samples of See Addendum Page

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 61010-1 Safety Requirements for Electrical Equipment

for Measurement, Control, and Laboratory Use - Part 1:

General Requirements

UL 61010-2-201, Safety Requirements for Electrical

Equipment for Measurement, Control, and Laboratory Use - Part 2-201: Particular Requirements for Control Equipment CSA-C22.2 No. 61010-1, Safety Requirements for Electrical Equipment for Measurement, Control, and Laboratory Use -

Part 1: General Requirements

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC





CERTIFICATE OF COMPLIANCE

20141115-E223772 Certificate Number E223772-20000724 **Report Reference** 2014-NOVEMBER-15 **Issue Date**

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL, CNL -Programmable Controllers -interface modules VAA or VBA followed by xE or followed by xExE or followed by vA or followed by xEyA or followed by zEA, may be followed by K2, K3, KE, KE1, KE2, KF, or KF2, G2, G11, G12 or G16, may be followed by E2, EA2, E2L, I, PT100, U, ZEJQ, WS, Z, ZA, ZE, ZE/E2, ZEJQ/E2L, ZE/R, Z/R, Z/E2, may be followed by J, L, or Q, may be followed by a combination of letters and /or numbers:

USL, CNL -Programmable Controllers, class 2 interface modules VAA or VBA followed by xE or followed by xExE or followed by yA or followed by xEyA or followed by zEA, followed by G4, may be followed by E2, I, PT100, U, ZE, ZE/E2, may be followed by J, L, or Q, may be followed by a combination of letters and /or numbers:

Note: Where x = number of inputs (max 4); y = number of outputs (max 4) and <math>z = number inputs (max 4)4) and outputs (max 4). Refer to pages 4 and 4a for full nomenclature.

Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, product a local UL Customer Service Representative at www.ul.com/contactus

