

Firmware Release Information

The following lists describe the implemented changes and fixed bugs of the different firmware versions.

Version 1.0.1 → 1.0.2

- ABB800xA interoperability fix
- General stability improvements

Version 1.0.2 → 1.0.3

- Interoperability bugfix with ABB800xA
- Allow access from multiple management tools like Siemens Proneta/Siemens Sinema server in parallel
- Fix **Restart with defaults** functionality
- General stability improvements

Version 1.0.3 → 1.0.4

- Fix (rare) IO data bump during S2 redundancy switchover