Software Release Notes



#### **Software Details**

Software Name:

Release Version: Release Date Description FDI Device Package Ethernet-APL Rail Field Switch ia 1.4.128 10/Jan/2024 FDI Device Package for Ethernet-APL Rail Field Switch ia



## 1. Software Version 1.4.128

## 1.1 Supported Products

ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.2.0

#### 1.2 New features

None

#### 1.3 Changed features

- Update of GSDML file
- Update of product documentation

#### 1.4 Bug Fixes

- Data rate for Dev port is not supported by device removed from FDI package
- SNMP community strings are not evaluated in FDI package whether they are valid
- Alert timestamp is shown as edited in some FDI hosts, although it is a read-only value



# 2. Software Version 1.3.103

## 2.1 Supported Products

ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.2.0

#### 2.2 New features

- Network communication load and communication error rates for Ethernet ports
- Communication statistics for PROFIBUS PA
- Alert reporting to a PROFINET controller (DCS alarming) can be disabled without disabling alerts shown at the web interface and FDI package
- Diagnostic shows hints about disabled or acknowledged alarms and disabled DCS alarming
- Status of the bulk power supply connection is shown at the diagnostics details of the device

#### 2.3 Changed features

Update of product documentation

#### 2.4 Bug Fixes

None



## 3. Software Version 1.2.85

## 3.1 Supported Products

• ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.1.1

#### 3.2 New features

None

#### 3.3 Changed features

- Update of GSDML file
- Update of product documentation

#### 3.4 Bug Fixes

None



# 4. Software Version 1.2.83

## 4.1 Supported Products

ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.1.1

#### 4.2 New features

- FDI Package supports more parameters in the offline configuration menu
- FDI Package is digitally signed

#### 4.3 Changed features

- Read performance of switch parameters is optimized for faster access
- Performance improvements for FDI Hosts using Common Host Components 1.5.1 (e.g. ABB Field Information Manager 2.4)
- Device information like serial number is also shown in the "Settings" menu as some FDI hosts don't provide the "Maintenance" menu

#### 4.4 Bug Fixes

 SNMP parameters cannot be changed if SNMP is enabled/disabled by a PROFINET AR

# 5. Software Version 1.1.55

#### 5.1 Supported Products

• ARS\*-\*-IA\*-\*, requires at least PANOS firmware version 1.1.0

#### 5.2 Changes

Initial Release



# Your automation, our passion.

#### **Explosion Protection**

- Intrinsic Safety Barriers
- Signal Conditioners
- FieldConnex<sup>®</sup> Fieldbus
- Remote I/O Systems
- Electrical Ex Equipment
- Purge and Pressurization
- Industrial HMI
- Mobile Computing and Communications
- HART Interface Solutions
- Surge Protection
- Wireless Solutions
- Level Measurement

#### **Industrial Sensors**

- Proximity Sensors
- Photoelectric Sensors
- Industrial Vision
- Ultrasonic Sensors
- Rotary Encoders
- Positioning Systems
- Inclination and Acceleration Sensors
- Fieldbus Modules
- AS-Interface
- Identification Systems
- Displays and Signal Processing
- Connectivity

Pepperl+Fuchs Quality Download our latest policy here:

www.pepperl-fuchs.com/quality



**EPPPERL+FUCHS** 

www.pepperl-fuchs.com

Änderungen vorbehalten · © PepperI+Fuchs Printed in Germany · DOCT-8196D