

Mounting aid for light grid of LG96 and LG192 series

Technical Data

| General specifications | |
|---------------------------|---------------------------------|
| Length | 620 mm |
| Accessories provided | Adhesive tape |
| Mechanical specifications | |
| Material | black anodized aluminum |
| Mass | 180 g |
| General information | |
| Scope of delivery | Mounting bracket, Adhesive tape |
| Suitable series | |
| Series | LG96 , LG192 |

 Refer to "General Notes Relating to Pepperl+Fuchs Product Information".


 Pepperl+Fuchs Group
 USA: +1 330 486 0001
 Gr

 www.pepperl-fuchs.com
 fa-info@us.pepperl-fuchs.com
 fa-info@us.pepperl-fuchs.com

Mounting

- 1. Ensure that the surface to be glued is free of grease and fluff.
- 2. Remove the protective paper from the adhesive tape.
- 3. Ensure that you do not touch the adhesive surface of the tape.
- 4. Immediately after removing the protective paper, press the mounting bracket onto the light grid.
- 5. The more evenly the mounting bracket is pressed on and the more force used, the better the surface contact will be.
- 6. The ideal working temperature is between + 15 $^\circ\text{C}$ and + 25 $^\circ\text{C}$

Mounting options



Refer to "General Notes Relating to Pepperl+Fuchs Product Information"

Pepperl+Fuchs Group www.pepperl-fuchs.com

2